



Food Program Official Inspection Report

Siskiyou County Community Development Department
 Environmental Health Division
 806 S. Main Street
 Yreka, California 96097
 phone: (530) 841-2100, fax: (530) 841-4076

Facility Name: JH Ranch	Permit # 000015
Address: 8525 Homestead Lane, Etna, CA	
Permit Holder: Second Wing Program	Permit To Operate: <input checked="" type="checkbox"/> Valid <input type="checkbox"/> Not Valid
Phone: 530-467-3486	E-mail: fleener@jhranch.com
Food Safety Certified Employee: Bob Fleener	Expiration Date: 02/2028

		MAJ	OUT	COS	
					The marked items represent Health Code violations and must be corrected as follows:
Protection Time/Temp.	1	Food Temp.			
	2	Prep./ Service			
	3	Storage/ Disp.			
	4	Frozen Food			
	5	Pure Food			
	6	Reused Food			
	7	Transportation			
Food Storage	8	Storage Fac.			
	9	Refrig. Units			
	10	Thermometer			
	11	Hazardous Mat.			
	12	Spoils			
Uten./Equip.	13	Wash/ Sanitize			
	14	Equip. Condition		X	
	15	Utensil Condition			
Employee	16	Storage			
	17	Handwashing			
	18	Employee Hygiene			
	19	Employee Habits			
Water	20	Food Cert./ Card			
	21	Water			
Waste	22	Cross Con.			
	23	Liquid Waste			
Vermin	24	Refuse			
	25	Rodents/ Insects			
Facilities	26	Animal/ Fowl			
	27	Ventilation			
	28	Doors			
	29	Floors		X	
	30	Walls - Ceilings		X	
	31	Toilet Fac.			
	32	Janitorial Fac.			
Misc.	33	Lighting			
	34	Clothing - Linen			
	35	Signs			
	36	Misc.			

ROUTINE INSPECTION CONDUCTED THIS DATE

14) Observed 2 prep sinks directly plumbed into sewer/wastewater system. Ensure both prep sinks are plumbed indirectly into the floor sinks with at least a 1" air gap above the flood level of the rim. Repair or correct within 90 days.

29) Observed damages to the floor in front of the walk-in freezer in the bottom production room. Ensure floors are finished as to be smooth, durable, cleanable, and non-absorbent. Repair within 90 days.

30) Observed missing ceiling panels in the first floor production room where food is packaged. Ceilings above food prep area are to be cleanable, durable, smooth, and nonabsorbent. Repair or correct within 90 days.

MAJ = Major violation OUT = Out of compliance COS = Corrected on-site	
Received By (Print): Bob Fleener	Received by (Signature): _____ Date: 05/22/2024
REHS (Print): Chalyn Dewey	REHS (Signature): _____ Phone: 530-841-2112

Facility Name: JH Ranch

The marked items represent Health Code violations and must be corrected as follows:

Received By (Print):
Bob Fleener

Received by (Signature):

Date:
05/22/2024

REHS (Print):
Chalyn Dewey

REHS (Signature):

Phone:
530-841-2112

Facility Name: JH Ranch

The marked items represent Health Code violations and must be corrected as follows:

Received By (Print):
Bob Fleener

Received by (Signature):

Date:
05/22/2024

REHS (Print):
Chalyn Dewey

REHS (Signature):

Phone:
530-841-2112

Facility Name: JH Ranch

The marked items represent Health Code violations and must be corrected as follows:

Received By (Print):
Bob Fleener

Received by (Signature):

Date:
05/22/2024

REHS (Print):
Chalyn Dewey

REHS (Signature):

Phone:
530-841-2112